



 **CAUTION**

- 1) Use within the specified conditions. No warranty is made over specified conditions of use.
- 2) Avoid measuring corrosive pressure medium or in catalysis, unless otherwise, it would be the cause of defects.
- 3) Avoid measuring pressure medium in high temperature, unless otherwise, it would be the cause of defects.
- 4) Avoid measuring flammable pressure medium, unless otherwise, it would be the cause of explosion or fire.
- 5) Avoid disassembling, taking off a part or changing it.