


Recommended hole diameter of the board and precautions for use

Recommended hole diameter of the board



Probe precautions for use

- •If it is pushed for more than 2/3 stroke, it may cause damage, so please use less than 2/3 stroke.
- •The life cycle varies depending on the number of times of repetition and usage environment.

All specifications are subject to change without notice.

Sales Office MKT TAISEI Co., Ltd.

TAISEI Co., Ltd. Head Office Sales Dept. Address : 6972 Shimo-Yoshida, Chichibu-shi, Saitama-ken, 369-1593, JAPAN. Phone : +81-494-77-1211 / FAX : +81-494-77-1415

Address : 3-10-8, Nohagi 1st Bldg, Minami-Ikebukuro, Toshima-ku, Tokyo, 171-0022, Japan. Phone : +81-3-3982-0029 / FAX : +81-3-3986-1537 Web Site : http://www.mkt-taisei.co.jp/ e-socket_probe-03